

M28


27 Feb 2023

Prepared for

Identified 89 Issues

Worsley







Issue 1

1

Crack

Complete ☐



Issue 2

2

Painting defect

Complete ☐



Issue 3

3

Finishing defect

Complete ☐



Issue 4

4

Shower panel leaking

Complete ☐



Issue 5

5

Door lock can't closing well

Complete ☐



Issue 6

6

Crack

Complete ☐

Issue 7

7

Control not level

Complete ☐




Issue 8

8

Door Finishing defect

Complete ☐



Issue 9

9

Finishing defect

Complete ☐



Issue 10

10

Painting defect

Complete ☐

Issue 11

11

Door lock stand not well
Door lock can't move smoothly

Complete ☐



Issue 12

12

Hot water weak

Complete ☐



Issue 13

13

Door painting defect

Complete ☐



Issue 14

14

Door Painting defect

Complete ☐



Issue 15

15

Door Finishing defect

Complete ☐





Issue 16

16

Out of service

Complete ☐



Issue 17

17

Door can't closing smoothly

Complete ☐



Issue 18

18

Painting defect

Complete ☐



Issue 19

19

Door Finishing and painting defect

Complete ☐



Issue 20

20

Crack and finishing defect

Complete ☐

Issue 21

21

Door Finishing defect

Complete ☐



Issue 22

22

Painting defect

Complete ☐





Issue 23

23

Painting defect

Complete ☐



Issue 24

24

Painting defect

Complete ☐





Issue 25

25

Painting defect

Complete ☐

Issue 26

26

Crack

Complete ☐

Issue 27

27

Finishing defect

Complete ☐

Issue 28

28

Crack

Complete ☐

Issue 29

29

Painting defect

Complete ☐

Issue 30

30

Finishing defect

Complete ☐




Issue 31

31

Painting defect

Complete ☐



Issue 32

32

Painting defect

Complete ☐



Issue 33

33

Door Finishing defect

Complete ☐



Issue 34

34

Radiator face defect

Complete ☐



Issue 35

35

Cleaning issues

Complete ☐

Issue 36

36

Finishing defect

Complete ☐




Issue 37

37

Finishing defect

Complete ☐



Issue 38

38

Window Handel Defect

Complete ☐



Issue 39

39

Finishing defect

Complete ☐





Issue 40

40

Seal

Complete ☐



Issue 41

41

Seal

Complete ☐



Issue 42

42

Crack

Complete ☐



Issue 43

43

Door Finishing defect

Complete ☐



Issue 44

44

Crack

Complete ☐



Issue 45

45

Crack

Complete ☐



Issue 46

46

Seal

Complete ☐



Issue 47

47

Seal

Complete ☐



Issue 48

48

Hole and painting defect

Complete ☐



Issue 49

49

Radiator function not well

Complete ☐

Issue 50

50

Finishing defect

Complete ☐





Issue 51

51

Finishing defect

Complete ☐



Issue 52

52

Crack

Complete ☐



Issue 53

53

Crack

Complete ☐



Issue 54

54

Finishing defect

Complete ☐



Issue 55

55

Crack and painting

Complete ☐

Issue 56

56

Ceiling Painting defect

Complete ☐





Issue 57

57

Lighting Seal

Complete ☐



Issue 58

58

Painting defect

Complete ☐



Issue 59

59

Painting defect

Complete ☐

Issue 60

60

Painting defect

Complete ☐




Issue 61

61

Painting defect

Complete ☐



Issue 62

62

Down light is missing at the kitchen cupboards

Complete ☐



Issue 63

63

Unknown function

Complete ☐



Issue 64

64

Unknown function

Complete ☐



Issue 65

65

Not happy for the cleaning

Complete ☐



Issue 66

66

Paper inside window

Complete ☐



Issue 67

67

Panel crack

Complete ☐



Issue 68

68

Finishing defect

Complete ☐



Issue 69

69

Fence damage

Complete ☐

Issue 70

70

0.5mm crack and hold

Complete ☐



Issue 71

71

Leaking

Complete ☐



Issue 72

72

Wrong direction

Complete ☐



Issue 73

73

Fence damage

Complete ☐



Issue 74

74

Mortar filter is needed

Complete ☐



Issue 75

75

Mortar filter is needed

Complete ☐



Issue 76

76

Mortar filter is needed

Complete ☐

Issue 77

77

Roof tussles is not in good condition

Complete ☐



Issue 78

78

Roof tile damage

Complete ☐



Issue 79

79

Tile laying is not good

Complete ☐



Issue 80
Assigned to Roof Tiles Crqck

80


Complete ☐



Issue 81
Door can't close well

81

Complete ☐



Issue 82
Door can't close smoothly

82

Complete ☐



Issue 83
Radiator top not function

83


Complete ☐



Issue 84
Tile not level

84

Complete ☐



Issue 85
Leaking

85

Complete ☐



Issue 86

86

Door Finishing defect


Complete ☐

Issue 87

87

Glass found defect

Complete ☐



Issue 88

88

Condensation in the glaze is not a normal condition

Complete ☐



Issue 89

89

Glass had defect and crack

Complete ☐